

Mercedes-Benz

VIN: W1N2539151F809911

Diesel

Généré le 2025-01-07 21:48



Compteur kilométrique

✓ Tout a l'air bien



Statut légal

✓ Tout a l'air bien



Dommage

✓ Tout a l'air bien



+31

Sources de données

Nous avons vérifié 900+ sources de données dans **35 pays**



Les partenaires

Ce rapport se base sur

Vol

Le véhicule est-il actuellement signalé comme volé ? A-t-il été volé par le passé ? A-t-il été retrouvé ?



Aucun problème détecté

Nous n'avons trouvé aucune indication démontrant que le véhicule ait été volé.



Note

Bases de données policières. Vérification des véhicules volés effectué dans **8 pays** :  +2

Voici ce que nous avons vérifié :



Actuellement déclaré volé

- ✓ Aucun enregistrement trouvé



Volé par le passé

- ✓ Aucun enregistrement trouvé

Statut actuel inconnu



Volé puis retrouvé

- ✓ Aucun enregistrement trouvé

Le véhicule a été retrouvé

Base de données de la police sur les véhicules volés – **vérification effectuée en :**



Tchéquie



Danemark



Lituanie



États-Unis



Slovaquie



Suède



Roumanie



Slovénie


Compteur kilométrique

Y a-t-il des signes de compteur kilométrique trafiqué ou des différences ?



Note

- Dernier kilométrage connu : 102 692 km
- 5 relevés de kilométrage trouvés



Relevés du compteur kilométrique

2020-02 **11 km**

2021-09 **25 514 km**

2022-10 **47 337 km**

2023-11 **77 489 km**

2024-11 **102 692 km**

Statut légal

Le véhicule a-t-il passé le contrôle technique ? A-t-il été marqué comme mis à la casse ?



Aucun problème détecté

Aucune information sur le statut juridique de ce véhicule n'a été trouvée.

Juridique



Contrôle technique

✓ Aucun enregistrement trouvé

Pas d'enregistrement de contrôle technique trouvé



Épave

✓ Aucun enregistrement trouvé

Rien n'indique que le véhicule a été déclaré comme épave

Dommage

Ce véhicule a-t-il été endommagé par le passé ? Quel était le montant des dommages ?

✓ **Aucun problème détecté**

Registre des dommages



Des inexactitudes peuvent parfois se produire, surtout lorsqu'on vérifie des véhicules plus anciens. Les ateliers de réparation clandestins peuvent déguiser illégalement les défauts et dommages d'un véhicule. Parfois, même les plaques VIN d'un véhicule peuvent être remplacées. Nous avons diverses méthodes pour détecter ces infractions, mais il est impossible de fournir une garantie à 100%.

Catastrophes naturelles

Le véhicule a-t-il été localisé dans la zone d'une catastrophe naturelle ?

✓ **Aucun problème détecté**

Le véhicule ne s'est pas trouvé dans la zone d'une catastrophe naturelle

Émissions

Combien d'émissions de CO₂ les véhicules de ce modèle/année produisent-ils ?

Note

Tranche d'émissions de CO₂ : B (135 g/km)

Émissions de CO₂

Émissions CO₂ de ton véhicule

135 g/km Classe **B**

Jusqu'à 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 et plus

Émission de CO₂ g/km

Spécifications et équipement

Quels sont les spécifications et l'équipement connus pour ce véhicule ?

Note

Vérifie que les spécifications et l'équipement de ce véhicule correspondent aux déclarations du vendeur.

Identification et spécifications techniques



Marque

Mercedes-Benz



Description

glc 220 d 4matic off-roader



Type de carrosserie

SUV



Année du modèle

2020



Déplacement moteur

2l



Puissance moteur

151 kW (202 hp)



Type de carburant

Diesel



Type de transmission

Automatique



Type de conduite

AWD



Position du volant

Volant à gauche



Catégorie

M1



Homologation

e1*2001/116*0480*36



Poids total

2 500 kg



Poids à vide

5 100 kg



Émissions de CO2

135 g/km

Équipement

D'origine, sortie d'usine

01U

MERCEDES-BENZ CONNECT - SERVICES FOR NAVIGATION

02J

INVALID CHANGEOVER OF WORLD MANUFACTURER TO MERCEDES-BENZ AG (ASF)

050

YOM X9/2

07B

OPERATING INSTRUCTIONS AND SERVICE BOOKLET-FRENCH

085

WORLD MANUFACTURER CONVERSION TO MERCEDES-BENZ AG

08U

MERCEDES-BENZ CONNECT - SERVICES FOR VEHICLE SETUP (HERMES)

09U

MERCEDES-BENZ CONNECT - VEHICLE MONITORING (HERMES)

0V1

SPEED/LOAD INDEX 103V

100A

IMITATION LEATHER

105A

IMITATION LEATHER - BEIGE

189

CHANGEOVER OF CO2MPAS-3

1B3

COMMUNICATION MODULE ECE VERSION

22P

LANE PACKAGE

234

BLIND SPOT MONITORING

235

ACTIVE PARKING ASSIST

243

ACTIVE LANE KEEPING ASSIST (CAMERA)

249

AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS

255B

MB-MOBILO WITH DSB AND GGD

258

COLLISION WARNING SYSTEM WITH FCW-STOP ACTIVE BRAKE APPLICATION

270

GPS AERIAL

274

TELEPHONE ANTENNA

294

KNEEBAG

2U1

RADIATOR SHUTTER

2U8

ALTERNATIVE REFRIGERANT

309

CUP HOLDER

30P

STOWAGE FACILITY PACKAGE

337B

INSTRUMENT CLUSTER/HU LANGUAGE - FRENCH

345

RAIN SENSOR

351

ECALL EMERGENCY CALL SYSTEM

355

PREINSTALLATION FOR RETROFITTING NAVIGATION SYSTEM

362

HERMES COMMUNICATIONS MODULE LTE

365

HARD DRIVE NAVIGATION

367

PRE-INSTALLATION FOR LIVE TRAFFIC INFORMATION

3U6

HU COUNTRY SET FOR ECE/ROW

421

9-SPEED AUTOMATIC TRANSMISSION

428

STEERING WHEEL GEARSHIFT BUTTONS/STEERING WHEEL GEARSHIFT PADDLES - PAINTED

440

CRUISE CONTROL

446

TOUCHPAD ONLY

463

FRONT VISUAL DISPLAY (HEAD-UP DISPLAY)

475

TIRE PRESSURE MONITOR (TPM)

485

COMFORT SUSPENSION

500

ELECTRICALLY FOLDING EXTERIOR MIRRORS

501

360° CAMERA

502

MULTI-YEAR FREE MAP UPDATES

531L

FRANCE

537

DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.)

548

CONNECT 20 MID (NTG6)

55U

HEADLINER, BEIGE FABRIC

580

AIR-CONDITIONING SYSTEM

5P6

CONTROL CODE FOR SALES

5XXL

EUROPE

611

AMBIENT LIGHTING

632

HEADLAMPS, LED, STATIC, RIGHT-SIDE TRAFFIC

64R

LIGHT-ALLOY WHEEL 5-TRIPLE-SPOKE DESIGN 18" "ALL-ROUND"

6P5

CONTROL CODE FOR SALES

723

LOAD COMPARTMENT COVER

725

ROOF RAILS IN CHROME LOOK

79B

PRE-INSTALLATION FOR DIGITAL RADIO STANDARD DAB/DMB

800

YOM X9/1

840

GLAS DUNKEL GETÖNT

846

RUNNING BOARD IN ALUMINUM LOOK WITH RUBBER NAPS

859

CENTRAL DISPLAY SIZE M

876

INTERIOR LIGHTING PACKAGE

890

AUTOMATIC REAR-END DOOR

890U

MANUFAKTUR CAVANSITE BLUE - METALLIC FINISH

893

KEYLESS-START

8U6

ASSISTANCE SYSTEM STEERING WHEEL CONTROL CHANGEOVER

8U7

REAR PASSENGER COMPARTMENT SEAT BELT WITH BELT FORCE LIMITER AND SOFTST.

8U8

I-SIZE MARKING (ISOFIX SUCCESSOR)

900

EXTERIOR CHROME PACKAGE

916

FUEL TANK WITH LARGE CAPACITY - VOLUME 1

927

EXHAUST TREATMENT, EURO 6 TECHNOLOGY

968

EURO 6 TECHNOLOGY COC DOCUMENT - WITHOUT MOTOR VEHICLE REGISTRATION CERTIFICATE, PART 2

971

EXHAUST SYSTEM WITH DPF, GENERATION 1.5

998

CONTROL CODE FOR CONVERSION TO WLTP WITH RDE

B51

TIREFIT

B59

DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)

F253

MODEL SERIES 253

FX

SPECIAL VERSION

GA

AUTOMATIC TRANSMISSION

H07

TRIM ELEMENTS - BROWN ZEN WOOD - FINELINE

HA

REAR AXLE

JVN

PLANT CONTROL CODE

JVO

PLANT CONTROL CODE

JWA

PLANT CONTROL CODE

K06

ENGINE POWER CATEGORY UNDER 151 KW

K11

ADAPTIVE BRAKE LIGHT, FLASHING

K13

CONTROL CODE FOR SERVICE INTERVAL 25000 KM

K27

SOFTWARE CONTROL FOR UNPOWERED IN POSITION "D"

L

LEFT-HAND DRIVE

L3E

SPORT STEERING WHEEL - SMOOTH SPLIT LEATHER

M005

VEHICLES WITH 4MATIC/ALL-WHEEL DRIVE

M20

DISPLACEMENT 2.0 LITER

M654

INLINE DIESEL ENGINE OM654

O48

SOFTWARE FRESH-UP 4

P22

EQUIPMENT LINE/PACKAGE – LUXURY – INTERIOR

P47

PARKING PACKAGE HIGH

P49

MIRROR PACKAGE

P65

ERGONOMICS PACKAGE

P76

EQUIPMENT LINE/PACKAGE – BASIC – EXTERIOR

PBF

MBUX NAVIGATION PLUS

PYA

CONTROL CODE FOR SALES

PYB

CONTROL CODE FOR SALES

PYD

CONTROL CODE FOR SALES

PYM

CONTROL CODE FOR SALES

PZB

CONTROL CODE FOR SALES

R01

SUMMER TYRES

U01

REAR SEAT BELT STATUS INDICATOR

U09

LEATHER-CLAD INSTRUMENT PANEL AND BELTLINE (EMBOSSSED IMIT.)

U10

FRONT PASSENGER SEAT WITH WEIGHT SENSOR

U12

VELOUR FLOOR MATS

U22

FRONT LUMBAR SUPPORT ADJUSTMENT

U35

12 V SOCKET IN LOAD COMPARTMENT

U60

PEDESTRIAN PROTECTION - ACTIVE HOOD

U79

BLUETEC SCR DIESEL EXHAUST GAS CLEANING, GENERATION 3

U82

USB CHARGE SOCKET IN REAR PASSENGER COMPARTMENT

U85

LARGE SCR TANK

VL

LEFT FRONT AXLE HALF

VR

RIGHT FRONT AXLE HALF

Chronologie

2 enregistrements trouvés

La chronologie des enregistrements pour ce véhicule

Derniers enregistrements

2020-02  France



A été immatriculé

Cet enregistrement représente le fait d'un évènement administratif. Il pourrait s'agir d'un changement de propriétaire, de documents, etc.

2024-12  France



Mis en vente

Cet enregistrement a été créé parce que le véhicule a été mis en vente sur une place de marché. Parfois, le pays (ou l'État) du vendeur remplace la localisation réelle du véhicule.



+31

Sources de données

Nous avons vérifié 900+ sources de données dans **35 pays**



Les partenaires

Ce rapport se base sur